

HIGHWAY STATISTICS

2011 Status of Delaware Automatic Traffic Recorder (ATR) Stations

There were approximately 1000 short-term counts taken in 2011 and 22 Weigh-in-motion stations were calibrated. All of our ATR sites were operational throughout the year, with the exception of locations that were off-line for repairs, or due to construction.

- Site 8004, located at I-495 by the Boulevard Body Shop, was out of service for volume counts the entire year due to a bad sensor.
- Site 8012, located at Foulk and Simon Road, was out of service for volume counts for the month of September, due to construction.
- Site 8016, located at US 301, north of Hooper Equipment, was out of service for volume counts for the months of February and March, due to construction.
- Site 8017, located at DE 896, north of the Summit Bridge, was out of service for the entire year, due to construction.
- Site 8022, located at DE 7, Limestone Rd at PA line, was out of service for the month of May, due to construction.
- Site 8026, located at DE 7, south of Little Baltimore, and was out of service for the months of January, February, and March, due to construction.
- Site 8028, located at U.S. 13, south of old St. Georges Bridge, was out of service for the months of January through May, due to construction.
- Site 8030, located at U.S. 202 at the PA line, was out of service for the month of July, due to no power at the site.
- Site 8037, located on DE 1 @ Paddock Road, was out of service for classification counts for the months of January and February.
- Site 8053, located on RD 315, Delaware State Fair, was out of service for the months of February and September, due to site issues.
- Site 8062, located at DE1 southbound to U.S. 113, was out of service for volume counts for almost the entire year, except for June and July, due to construction.
- Site 8067, located on RT. 12, Burnite Mill Road, was a new site added in May 2011.
- Site 8068, located on RT. 14, Burrsville Road, was a new site added in May 2011.
- Site 8069, located on DE 404, Wooden Hawk, was out of service for WIM counts for the months of April and May.
- Site 8073, located on DE 18, west of Georgetown, was out of service for WIM counts for the month of August.
- Site 8074, located on U.S. 113, south of Georgetown, and was out of service for volume counts for the month of February, classification counts for the months of April and May, and WIM counts for the months of August and September, all due to a bad lane.

- Site 8075, located on DE RT 1, south of DE 16, was out of service for volume counts the month of February, due to a bad lane.
- Site 8077, located on DE 1, Fenwick, was out of service the months of November and December, due to construction.
- Site 8082, located on US 113, Georgetown, was out of service the month of December, due to construction.
- Site 8091, located on DE 1, Barratts Chapel, was out of service March through December, due to construction.
- Site 8092, located on DE1 and 10th Street, was out of service for volume and classification counts the month of October.
- Site 8094, located on US 113, south of 625, Lincoln, was out of service for classification counts the month of March.

Phil Petrucci, Senior Application Support Specialist
Office of Information Technology
Delaware Department of Transportation
Tel: 302-760-2865 Cell: 302-222-1051
philip.petrucci@state.de.us

DelDOT Division of Planning

www.deldot.gov/information/projects/hpms